



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Caesar Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 21, 2010

Karl Hasenstab
Continental/Olentangy Hotel LLC
150 East Broad Street 8th Floor
Columbus, OH 43215

**Re: Construction Storm Water Inspection at Springhill Suites by Marriott / Franklin County
Permit Number 4GC03232*AG**

Dear, Mr. Hasenstab:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley of Ohio EPA at Springhill Suites by Marriott in Columbus, Ohio on July 8, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The stockpile along the eastern most side of the project area lacks appropriate sediment and erosion control. Corrective measures to install silt fencing and cover is expected within three days upon receipt of this letter. (Figure 1)
- There are no sediment controls around the storm drain access point shown in figure 2. It is evident that sediment could bypass the manhole cover through the open point shown in the photo. Corrective measures are expected to eliminate this by-pass with three days upon receipt of this letter.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Springhill Suites by Marriot

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korteski, Director








Figure 1: Stockpile along fence line




Figure 2: Sediment Bypass point noted by spray can top

