



**Environmental
Protection Agency**

Tim Strickland, Governor
Lee Fisher, Lt. Governor
Chris Konecki, Director

August 9, 2010

RE: SUMMIT COUNTY
LITTLE CUYAHOGA RIVER BASIN
CITY OF AKRON
WINDEMERE COMMUNITY LEARNING CENTER

Mr. Gerry Taylor
70 N. Broadway Avenue
Akron, OH 44308

Dear Mr. Taylor:


On August 3, 2010, Ohio EPA conducted a follow-up inspection of the Windemere Community Learning Center project, located at 2283 Windemere Avenue, City of Akron, Summit County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04419*AG. I was accompanied by Lindsey Olmstead of Ohio EPA. The inspection documented the following:

- Sediment deposition was observed within the proposed biofilter areas (Figure 1). Remove all sediment before constructing the biofilters.
- Offsite tracking was observed (Figure 2). Reinstall and maintain the construction entrance in accordance with the site's SWP3. Mud spilled, dropped, washed or tracked onto public roads shall be removed immediately by scraping or sweeping. Offsite tracking was also observed at a rear entrance (Figure 3). Ensure all construction traffic is using the main construction entrance.
- Inlet protection has been damaged (Figure 4). Repair or reinstall inlet protection as necessary.
- The concrete washout pit was observed to be poorly constructed (Figure 5). Reinstall the concrete washout pit in accordance with the site's SWP3.
- Mortar and grout runoff was observed entering the biofilter area near the batching facilities (Figure 6). Use BMPs to prevent mortar and grout runoff from discharging into the biofilter areas.
- Silt fence had been torn or damaged. Repair or reinstall silt fence in accordance with the site's SWP3.

Mr. Gerry Taylor
Windemere Community Learning Center
August 9, 2010
Page 2

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1128.

Sincerely,

A handwritten signature in black ink, appearing to read 'Sean Green', written over a horizontal line.

Sean Green
Assistant to the District Engineer
Division of Surface Water

SG/mt

cc: Jason Huth, RPJ Construction Managers
Joan Hug-Anderson, Summit SWCD



Figure 1. The sediment and other material will need to be removed from the biofilters before installation of the biofilters.



Figure 2. Offsite tracking was observed at the main construction entrance.



Figure 3. Offsite tracking was observed at a rear construction entrance.




Figure 4. Inlet protection has been damaged.



Figure 5. The concrete washout pit needs to be reconstructed.




Figure 6. Runoff from mortar and grout activities is flowing into the biofilter area.