



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

July 7, 2010

RE: SUMMIT COUNTY
SPRINGFIELD LAKE OUTLET BASIN
CITY OF AKRON
HYRE COMMUNITY LEARNING CENTER

Mr. John George
70 N. Broadway Avenue
Akron, OH 44308

Dear Mr. George:

On June 17, 2010, Ohio EPA conducted an inspection of the Hyre Community Learning Center project located at 2443 Wedgewood Drive, City of Akron, Summit County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04518*AG. The inspection documented the following:

- Improper inlet protection has been installed around the site's storm sewer inlets (Figures 1 and 2). Much of the inlet protection has been damaged. Heavy sediment deposition was observed around the storm sewer inlets. Remove existing inlet protection and reinstall in accordance with the site's storm water pollution prevention plan (SWP3).
- Silt fence has been damaged and improperly installed (Figure 3). Silt fence near the rear of the site has been covered by an access ramp (Figure 4). Sediment deposition was observed at the rear of the site along the offsite hillside. Reinstall silt fence in accordance with the site's SWP3.
- A concrete washout pit was observed to be in need of maintenance (Figure 5). Reinstall the concrete washout pit in accordance with the site's SWP3 and maintain as necessary. Concrete washout was observed in random areas throughout the site (Figure 6). Ensure all concrete traffic is using the washout pits provided.
- Some areas of the site appeared to be idle for long periods of time (Figure 7). Stabilize all areas that will remain idle for a period of 21 days or longer or that are at final grade.
- Large amounts of trash and debris were observed throughout the site (Figure 8). Properly dispose of all trash and debris.

MR. JOHN GEORGE
JULY 7, 2010
PAGE 2

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. A copy of the site's SWP3 must be submitted to Ohio EPA for review within 10 days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1128.

Sincerely,



Sean Green
Assistant to the District Engineer
Division of Surface Water

SG:bo

cc: RPJ Construction Managers
Joan Hug-Anderson, Summit SWCD
Kelvin Rogers, Ohio EPA, DSW, NEDO




Figure 1. Improper inlet protection has been installed and damaged.




Figure 2. Improper inlet protection has been installed and damaged.



Figure 3. Silt fence has been damaged.



Figure 4. Silt fence has been buried underneath a constructed access road.



Figure 5. The concrete washout is in need of maintenance.



Figure 6. Concrete washout was observed in various areas throughout the site.



Figure 7. Any areas of the site that will remain idle for 21 days or longer will need to be temporarily stabilized.



Figure 8. Large amounts of trash and debris were observed throughout the site.