



State of Ohio Environmental Protection Agency

Southwest District Office

401 East Fifth Street
Dayton, Ohio 45402-2911

TELE: (937) 285-6357 FAX: (937) 285-6249
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

August 13, 2008

Paul Ryan, Site Manager
Chevron Environmental Management Company
6111 Bollinger Canyon Road
San Ramon, California 94583

RE: Compliance Evaluation Inspection
NPDES Permit No. 11G00000*FD
Hamilton County

Dear Mr. Ryan:

On July 23, 2008, I performed a compliance evaluation inspection at the ground water treatment system for the Chevron Products – Cincinnati facility located at 5000 State Route 128 in Hooven, Ohio. Dale Barrett with TriHydro accompanied me on this inspection. I have attached a copy of the inspection report and findings for you to review. All areas evaluated received a satisfactory rating. If you have any questions regarding the inspection, please call me at (937) 285-6101.

Sincerely,

Mary Osika
Environmental Specialist
Division of Surface Water

Enclosure

Cc: Chris Aneiros/Dale Barrett, TriHydro





Summary of Findings/Comments

A review of the monthly operating reports submitted to Ohio EPA since May, 2007 to the present showed 2 permit limit excursions at outfall 003 as summarized below:

<u>Date</u>	<u>Parameter</u>	<u>limit</u>	<u>reported value</u>
7/2007	Total Suspended Solids	179 kg/d	188 kg/d
7/18/2007	Total Suspended Solids	296 kg/d	373 kg/d

The average daily flow rate for the past year has been approximately 3.0 MGD for outfall 003.

There was no flow discharging from the outfalls at the time of the inspection. This is due to the ground water levels not being at the proper trigger levels for ground water clean up and recovering the hydrocarbons.

