



4GC0289520100920

2010/09/20

4GC02895

PRESCOTT PLACE



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

September 20, 2010

Joe Thomas Junior
Metro Development LLC
470 Olde Worthington Road, Suite 100
Westerville, OH 43082

**Re: Construction Storm Water Inspection at Prescott Place / Franklin County
Permit Number 4GC02895*AG**

Dear Mr. Thomas:

This letter is written in follow-up to a construction storm water inspection I conducted at Prescott Place located south of Hutchinson Avenue and north of I-270, Columbus, Ohio on August 19, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water permit, the following items were noted;

Sediment and Erosion Control:

- I noted a storm sewer discharge on the south end of the site into the stream west of the tributary (See Photo). Please ensure this discharge is treated in accordance to the construction requirements of the permit.
- Please submit the design criteria for the sediment basins.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, CDO/DSW

HK/nsm Prescott Place 7-16-2010

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director








Figure 1: Storm sewer discharge on south end

