



State of Ohio Environmental Protection Agency

REET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

August 24, 2010

Glenn Schultz
Woda Construction Incorporated
229 Huber Village Boulevard, Suite 100
Westerville, OH 43081

**Re: Storm Water Inspection at Honeybrook Greene / Licking County
Permit No: 4GC03080*AG**

Dear Mr. Schultz,

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley and Michael Shields of Ohio EPA at the Honeybrook Greene located in the vacant parcel northwest of North Street on August 09, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following was noted:

Sediment and Erosion Control:

- The perimeter silt fence on the north side of the property adjacent to the tributary running along the property must be properly maintained to minimize off site sedimentation (see figure 1).
- Please be aware the general permit states that all sediment controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches to ensure continued effectiveness of the sediment basin.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.


Sincerely,


Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Honeybrook Greene

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director





Fort Monmouth, New Jersey
Top of River Wall
Photo by Stephen R. Kelly, USACE
August 9, 2010
Note: Silt fence in disrepair and in need of repair.
North side of property

Figure 1: Silt fence in disrepair

