



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 12, 2010

Karen Koch
Concord Township
7860 Dublin Road
Delaware, OH 43015

**Re: Construction Storm Water Inspection at Concord Township Building / Delaware County
Permit Number 4GC03204*AG**

Dear Mr. Hoyt:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley, Vinod Tujalpuram, and Jed Plank of Ohio EPA at Concord Township Building in Delaware, Ohio on June 30, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- There is minimal sediment control at the outlet of the sediment basin under construction (Please refer to Figure 1). Sediment traps must be utilized for areas of concentrated flow and must be sized with a required sediment storage volume per the General Permit. These sediment impoundments will require cleaning once they have exceeded 50 percent of their capacity.
- There is minimal sediment control around the perimeter of the site. (Please refer to figure 2). I suggest installing silt fencing that completely encompasses the area of disturbance.
- There is an inadequate amount of control at the major access point off of Home Road (Please refer to figure 3). I suggest more gravel, approximately 50 feet from the public road.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Concord Township Building

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director








Figure 1: Inadequate silt fence along south side of property



Figure 2: Inadequate sediment controls for sediment basin






Figure 3: Inadequate sediment controls at main access point

