



\*4GC0343720110803\*

2011/08/03

4GC03437

AMBERLEIGH COMMUNITY PARK



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

August 4, 2011

Fred Hahn  
Jess Construction  
3369 Schnorf Jones Road  
Arcanum, OH 45304

**Re: Construction Storm Water Inspection at Amberleigh Community Park  
Franklin County  
Permit Number: 4GC03437 \*AG**

Dear Mr. Hahn:

This letter is written regarding a storm water inspection conducted by Greg Mann and Kelsey Heyob of the Ohio EPA at Amberleigh Community Park located at 4715 Vista Ridge Drive, Dublin Ohio on July 22, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- Our staff noted that perimeter silt fence has failed along the lower (eastern) side of the site. Please perform the necessary maintenance to ensure the silt fences are functioning as intended and offsite sediment transport is minimized (See Figure 1).
- During the inspection our staff noticed improper concrete disposal near the entrance of the site. Please employ corrective measures to implement a proper concrete disposal area (See Figure 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office


Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/nsm Amberleigh Community 7-22-11

Central District Office  
50 West Town Street, Suite 700  
P.O. Box 1049  
Columbus, OH 43216-1049


614 | 728 3778  
614 | 728 3898 (fax)  
[www.epa.ohio.gov](http://www.epa.ohio.gov)





Amherstleigh Community Park  
Photo Taken By: Greg Mann  
Santo Watershed  
Failed Perimeter Barrels

Figure 1



Amherstleigh Community Park  
Photo Taken By: Greg Mann  
Santo Watershed

Concrete Washout Area Not Contained

Figure 2

