



4GC0334220110726

2011/07/26

4GC03342

RICH PRODUCTS PRETREATMENT FACILITY



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 26, 2011

Michael Anderson
Bird and Bull Engineering
2875 West Dublin Granville Road
Columbus, OH 43235

Re: **Construction Storm Water Inspection at Rich Products Pretreatment Facility
Franklin County
Permit Number: 4GC03342 *AG**

Dear Mr. Anderson:

This letter is written regarding a storm water inspection conducted by Daelann Farnlacher and Kelsey Heyob of the Ohio EPA at Rich Products Pretreatment Facility located at 4600 Northwest Parkway Hilliard, Ohio on July 11, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. This letter also serves as a **Notice of Violation (NOV)** for failure to meet conditions of the General Permit. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- During the inspection, our staff noted the sediment basin on site does not have an appropriate outlet structure (See Figure 1). Please install a modified sediment control outlet structure such as a temporary riser or skimmer within seven days from receipt of this letter to ensure compliance.
- The staff also noted a bypass into a storm sewer drain shown in Figure 2 which requires maintenance.
- It was noted that a storm sewer drain requires appropriate inlet protection to minimize the discharge of sediment into waters of the state (See Figure 3).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our *Central District Office* at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO





Figure 1: Sediment basin requires modified outlet structure




Figure 2: Bypass into storm drain






Figure 1: Storm drain requires inlet protection

