



\*4GR0037520110726\*

2011/07/26

4GR00375

WESTERVILLE SATELITE FACILITY



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 26, 2011

Jerry Bennett  
Kurtz Brothers Central Ohio LLC  
6055 Westerville Road  
Westerville, OH 43081

**Re: Industrial Storm Water Inspection at Westerville Satellite Facility  
Franklin County  
Permit #: 4GR00375\*BG**

Dear Mr. Bennett:

This letter is written in follow-up to an industrial storm water inspection conducted by Lauren Burns and Lindsey Boaz at Westerville Satellite Facility located at 6055 Westerville Road Westerville, Ohio on July 1, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with industrial activities. During the inspection, the following items were noted:

**Containment Measures:**

- The berm containing the mulch piles appears to be functioning properly for the majority of the area. However, during the inspection it was noted that a section of the northwest mulch pile berm was damaged and leaching water (see Photo Figure 1). Please repair and continue to maintain these berms within seven days of receipt of this letter.
- Additional berms must be maintained for the waste drop off area, specifically adjacent to Alum Creek.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844. In addition, please provide a written response to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Kurtz Brothers

Central District Office  
50 West Town Street, Suite 700  
P.O. Box 1049  
Columbus, OH 43216-1049

614 | 728 3778  
614 | 728 3898 (fax)  
www.epa.ohio.gov






Figure 1: Damaged berm in need of repair.

