



4GCO000520110712

2011/07/12

4GCO0005

TURKEY HILL MINIT MARKET #707



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 12, 2011

Steve Fuller
TH Midwest, Inc.
2600 Corporate Exchange Dr., Suite 170
Columbus, OH 43231

**Re: Construction Storm Water Inspection at Turkey Hill Minit Market #707
Franklin County
Permit Number: 4GCO00053*AG**

Dear Mr. Fuller:

This letter is written regarding a storm water inspection conducted by Daelann Farnlacher and Greg Mann of the Ohio EPA at Turkey Hill Minit Market #707 located at 2740 Stratford Road, Dublin, Ohio on June 22, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Sediment controls for this project must be implemented in accordance with the General Storm Water Permit. Our staff noted failed silt fencing along the north end of the perimeter by State Route 62 which must be maintained (See Figure 1).
- According to the Storm Water Pollution Prevention Plan, the sediment basin was required first in the construction sequence. Please install the sediment basin and ensure all barren areas are routed to the impoundment intended for sediment control within seven days of receipt of this letter.
- A stabilized construction entrance must be provided to minimize the vehicle tracking of mud onto public roads (See Figure 2).

Steve Fuller
TH Midwest, Inc.
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO


HK/nsm Turkey Hill #707



Figure 1: Failed silt fence



Figure 2: Entrance to site



Conrad Strapping Systems
Licking River Watershed
Photo By: Eselana Farblacher
6/14/11
Discharge to storm sewer system

Figure 1: Concrete waste discharge

