



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

January 20, 2010

Jeffrey D. Wallace
Allen Milk Company
A Division of T. Marzetti Company
1709 Frank Road
Columbus, OH 43223

**Re: Allen Milk Company, A Division of T. Marzetti Company / Franklin County
Industrial Storm Water Permit 4GR00065*DG**

Dear Mr. Wallace:

This letter is written in regard to the storm water inspection that I conducted at Allen Milk Company, A Division of T. Marzetti Company, located at 1709 Frank Road in Columbus, Ohio. The inspection was conducted on January 19, 2010, to determine compliance with your industrial storm water permit. The company makes vegetable dips and sauces for the food industry. Milk and sour cream were the main ingredients of your products. There were no pollutants discharging to storm water drains or to waters of the state. Overall, the facility was well-kept. The following items were noted during the inspection:

1. The property had a fire that caused damage to the blower room. Temporary blowers were being used and located outside. Secondary containment was being used for the fuel tank of the blowers. However, a small amount of fuel had spilled on to the parking lot near the temporary blowers. There was an oily sheen in a small puddle in the parking lot. You stated that the new blower building would be ready in approximately a week and the temporary blowers would then be removed from the parking lot. You also stated that the parking lot would be steam cleaned.
2. The facility had all outside tanks in either secondary containment or used double-walled tanks. No evidence of product staining the parking lot or storage areas.
3. The facility had a storm water pollution prevent plan and a spill prevention plan.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Jeffrey D. Wallace
Allen Milk Company
A Division of T. Marzetti Company
Page -2-

4. A sump pit was located near the loading dock located on the west side of the building. The sump pit had the drain plugs removed due to freezing of the sump pit. The sump pit was manually operated. No evidence of pollutants discharging to the storm water drain.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,




Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosures

c: Jeff Bohne, DSW/CDO

GS/nsm Allen Milk Company., January 19, 2010

Allen Milk Company
Temporary blower system
Scioto River Watershed
January 18, 2010
Photo by: Greg Sanders



Allen Milk Company
Oily sheen in puddle
Scioto River Watershed
January 18, 2010
Photo by: Greg Sanders







Allen Milk Company
Sump from Loading Dock
Saguaro River Watershed
January 19, 2010
Photo by: Craig Sanders

