



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 17, 2009

RE: PILOT TRAVEL CENTERS LLC
SITE NO. 011
10920 MARKET STREET
NPDES PERMIT NO. 3IG00066*BD

Mr. Jason McCain
Pilot Travel Centers
5508 Lanas Road
Knoxville, TN

Dear Mr. McCain:

On February 13, 2009, this writer conducted an inspection of the storm water pond for the Pilot Travel Center #011. For several days prior to the inspection, the area experienced a significant snow melt and rain event. The intent of the inspection was to determine the quality of effluent discharging from the facility at the time of the inspection as a result of the weather conditions.

At the time of the inspection the outlet structure was the 12 inch pipe at the bottom of the pond. Water was discharging from the pond at approximately 1-2 gpm. The effluent was clear and had no oil sheen. A slight sheen was identified towards the middle of the pond; however, it did not appear to be migrating to the outlet.

The new outlet structure had not been installed at the time of the inspection. Be advised that once you receive the permit-to-install from Ohio EPA, you will have one month to initiate construction and 2 months to complete construction of the approved structure. This is a requirement of Part I.C of the NPDES Permit for the facility.

It is recommended that the maximum water elevation in the pond following construction of the outlet structure be compared to the invert elevation for the discharge pipe from the oil/water separator. This should be done to ensure that storm water does not back-up into the separator.


A review of the compliance record was conducted for the period covering January 2008 through December 2008. One limit violation and no frequency violations were identified during the review period. Following is the limit violation reported during the review period.

Date	Station	Parameter	Limit	Reported Value
Feb. 20, 2008	001	pH	6.5 min.	6.42

Mr. Jason McCain
Pilot Travel Centers
February 17, 2009
Page 2

You may contact this office at (330) 963-1251 to discuss any questions you may have regarding this inspection report. A follow-up inspection will be conducted to confirm installation of the new outlet structure.

Respectfully,

A handwritten signature in black ink, appearing to read "John Kwolek". The signature is written in a cursive style with a large initial "J".

John Kwolek
District Engineer
Division of Surface Water

JK/mt

cc: Theresa M. Perline, Travel Center General Manager, Pilot Travel Center