

**Environmental  
Protection Agency**

Ted Strickland, Governor  
Lee Fisher, Lt. Governor  
Chris Grady, Director

July 13, 2010

RE: CUYAHOGA COUNTY  
TINKERS CREEK BASIN  
CITY OF MAPLE HEIGHTS  
NEW STAFFORD MIDDLE SCHOOL

Mr. Christopher Krause  
14605 Granger Road  
Maple Heights, OH 44137

Dear Mr. Krause:

On July 7, 2010, Ohio EPA conducted an inspection of the New Stafford Middle School project located at 19800 Stafford Avenue, City of Maple Heights, Cuyahoga County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04506\*AG. I was accompanied by Jason McLeod and Brian Gagne of Heery/Stevens Construction and Chris Jensen of Platform Cement Company. The inspection documented the following:

- Sediment basin #1 (SB1) was being installed at the time of inspection. Ensure the outlet structure and skimmer are installed in accordance with the site's storm water pollution prevention plan (SWP3).
- Inlet protection around inlet #2 (IP2) appears to have been breached (Figure 1). Ensure the inlet protection has been installed properly. Repair or reinstall inlet protection in accordance with the site's SWP3.
- The rock check dam in TD3 as it enters into sediment trap #2 (ST2) was observed to be in need of repair (Figure 2). Repair or reinstall the rock check dam in accordance with the site's SWP3.
- There were issues with the installation of the silt fence along the east end of the site. Observations showed the backfill material to be unsuitable, wet or dry. Mr. Jensen stated that he would discuss the issue with Christopher Hartman of Chagrin Valley Engineering.

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1128.

Sincerely,



Sean Green  
Assistant to the District Engineer  
Division of Surface Water

SG/mt

cc: Christopher Hartman, Chagrin Valley Engineering, Ltd.  
Jason McLeod, Heery International  
Dan Bogoevski, Ohio EPA, DSW, NEDO




Figure 1. Water appears to have found its way underneath the inlet protection.



Figure 2. The rock check dam in TD3 is in need of repair.