





Figure 1. Catch basins still missing inlet protection.



Figure 2. inadequate inlet protections have still not been replaced.



Figure 3. Leaking equipment still on site.



Figure 4. Concrete wash out still visible on site.



Figure 5. Tree lawns still aren't stabilized.