



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

July 6, 2010

RE: LORAIN COUNTY
BLACK RIVER BASIN
CITY OF ELYRIA
EAST RIVER STREET

Mr. Mukund Moghe
131 Court Street
Elyria, Ohio 44035

Dear Mr. Moghe:

On June 15, 2010, Ohio EPA conducted an inspection of the East River Street project located along East River Street from the southern corp. limit to East Broad Street, City of Elyria, Lorain County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04759*AG. I was accompanied by Chris Moody of Ohio EPA. The inspection documented the following:

- Improper or no inlet protection has been installed (Figure 1). Install inlet protection in accordance with the site's storm water pollution prevention plan (SWP3). The specification for erosion and sediment best management practices can be located in the Ohio Department of Natural Resources' Rainwater and Land Development Manual which is available from the following website:

<http://www.dnr.state.oh.us/water/rainwater/default/tabid/9186/Default.aspx>

- Silt fence has not been installed in many areas throughout the site (Figure 2). Install silt fence in accordance with the site's SWP3.
- Many areas of the site appear to be ready to be stabilized (Figure 2). Please stabilize all areas that are to remain idle 21 days or longer and all areas that are at final grade.

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1128.

Sincerely,

Sean Green
Assistant to the District Engineer
Division of Surface Water

SG:bo

cc: Mr. Excavator, Inc.
Dan Bogoevski, Ohio EPA, DSW, NEDO



Figure 1. Improper inlet protection has been installed.



Figure 2. Silt fence has not been installed as shown on the site's SWP3. Also, many areas of the site appear ready to be stabilized.