



**Environmental  
Protection Agency**

Technical Support, Governor  
Lee H. Fisher, Lt. Governor  
Christina Beardsley, Director

July 19, 2010

RE: MAHONING COUNTY  
CRAB CREEK BASIN  
CITY OF YOUNGSTOWN  
WATTS INDOOR FACILITY

Mr. John Hyden  
One University Plaza  
Youngstown, OH 44555

Dear Mr. Hyden:

On July 15, 2010, Ohio EPA conducted an inspection of the Watts Indoor Facility project, located along the eastbound service road between Elm Street and Wick Avenue, City of Youngstown, Mahoning County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04792\*AG. The inspection documented the following:

- No inlet protection has been installed at the curb inlets along the eastbound service road between Elm Street and Wick Avenue (Figure 1). Install inlet protection in accordance with the site's storm water pollution prevention plan (SWP3).
- Heavy offsite tracking of sediment was observed (Figure 2). Minimize the offsite tracking of sediment through scraping or sweeping. It may be necessary to reinstall the construction entrance.
- Dust control appears to be a major issue on-site (Figure 3). Minimize dust generation through watering activities and street sweeping.
- Silt fence has been damaged (Figure 4). Repair or reinstall silt fence in accordance with the site's SWP3.

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience by phone at (330) 963-1128, or by email at [Sean.Green@epa.state.oh.us](mailto:Sean.Green@epa.state.oh.us)

Sincerely,

Sean Green  
Assistant to the District Engineer  
Division of Surface Water

SG/mt

cc: Ryan Hively, Hively Construction Co.

**Northeast District Office**  
2110 East Aurora Road  
Twinsburg, OH 44087-1924

330 | 963 1200  
330 | 487 0769 (fax)  
[www.epa.ohio.gov](http://www.epa.ohio.gov)



Figure 1. Inlet protection has not been installed at the curb inlets along EB Service Road.



Figure 2. A heavy amount of offsite tracking was observed.



Figure 3. A large amount of dust was observed.




Figure 4. Silt fence was observed to be damaged.