

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: ewc

Visit date: 8/27/12 Permit # 16C04234-AG

Site Name: Beechmont Ashbury

Site Address: 7735 Beechmont Ave, Cincinnati OH

People contacted on site (attach business cards): Scott Burch

Their phone and e-mail: 513-265-2032 CCC

1. Did you see the following on site?

ITEM	Yes/No	Not requested	Comments
NOI	No		Paperwork in office.
Coverage letter			
SWP3			
Inspection records	Yes		
Contractor & Subs signature document			

2. Acreage disturbed (circle): < 1 acre 4-6 >1 but <5 acres >5 but <10 acres >10 acres ??

3. Site status: Clearing/grubbing Rough grading Storm sewers in Streets in  
 Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? Yes Southern side has a lot of grade to creek + Inlet protection

5. Are BMPs on site effective? All Some None No BMPS

Explain: One CB at entrance needed repair

6. What post construction controls are shown on the SWP3? Underground Retention

7. Were photos taken and saved? Yes

8. Was an NOV issued? No

Notes:

- Close to final grade on South Bank.  
↳ Seeding by end of the week.