



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

March 19, 2013

RE: SUM-SEIBERLING PHS 2
3GC05686*AG
STORMWATER
SUMMIT COUNTY

Mike Teodecki,
City of Akron Bureau of Engineering
166 S. High Street
Akron, Ohio 44308

Ray Kinney
Site Manager
Sitetech
35700 East Royalton Road
Grafton, Ohio 44044

Gentleman:

This office is in receipt of your letter dated March 15, 2013, in response to our inspection letter dated March 4, 2013, concerning Sum-Seiberling Way Phs 2. We would like to follow up with several items listed in the permit concerning the responses.

Item 4

This item concerns the "small sediment trap" installed west of Haley's Ditch near the downstream side of the culvert. Please state whether or not this is intended to be a sediment trap or a sediment pond. Provide the total acreage draining to this device. Provide all calculations concerning the design of this device. Please be aware that whether it is a sediment trap or sediment basin it must be designed in accordance with the criteria specified or referenced in the general permit.

Item 6 and Action Item 2

The swale located west of the Massillon Road entrance is not shown on the Storm Water Pollution Prevention Plan (SWPPP) plan or your revisions to date. All BMP's must be shown in detail within the SWPPP. This office has repeatedly requested in writing that the City address this area between Massillon Road and Haley's Ditch. You are required to submit this information and any other information pertinent to compliance with the Construction General Permit as allowed under Part V.E. This is a continuing violation of the permit.

Action Item 3

We are in receipt of the SWPPP for Eagle Street. We request that you submit a copy of the written approval of this SWPPP from the City or Summit SWCD.

Action Item 4

The site inspection form does not individually list the location of the BMP's that need to be maintained. Please amend the form to either individually describe each BMP or provide a drawing identifying the location of the BMP on the site. The inspection must indicate whether or not each BMP is present and functioning as designed.

You are requested to adequately address the above listed items no later than April 2, 2013. If you should have any questions concerning any of the above, feel free to contact this writer at (330)963-1136 or by e-mail at phil.rhodes@epa.state.oh.us.

Sincerely,

Philip P. Rhodes, P.E.
Environmental Specialist II
Division of Surface Water

PPR/cs

ec: Ray Kinney
Fred Fassnacht
Mike Wytryszczewski
Allison Giancola, Ohio EPA, DMWM, NEDO
Dave Dysle, Ohio EPA, DMWM, NEDO