



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott A. Walky, Director

April 11, 2013

Jim Lipnos  
Homewood Cooperation  
2700 East Dublin Granville Road  
Columbus, OH 43231

**Re: Construction Storm Water Inspection at Hamilton Run Mass Fill  
Franklin County, Permit Number: 4GCD00080 \*AG**

Dear Mr. Lipnos:

This letter is written regarding a storm water inspection I conducted at Hamilton Run Mass Fill located along the west side of Alton Darby Creek and north of new Roberts Road on April 4, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, the following items were noted:

**Sediment and Erosion Control:**

- The fill site is protected from erosion with a mulch cover as previously requested. Additional protection measures are required this growing season to ensure the establishment of an effective vegetative cover measured by minimum density of 70 percent. Based on this inspection, the minimum density requirement is not established.
- Please continue to monitor the sediment impoundment in accordance with the conditions of the "General Storm Water Permit Associated with Construction Activities within the Darby Watershed."

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Hamilton Run Mass Fill 4-4-2013