

John R. Kasich, Governor
Wendy Torres, Lt. Governor
Scott J. R. ... , Director

May 29, 2013

John Amstutz
Columbia Gas of Ohio / NiSource Co.
1600 Dublin Road
Columbus, OH 43231

**Re: Construction Storm Water Inspection at Oakwood Avenue / Franklin County
Permit Number: 4GC04118 *AG**

Dear Mr. Amstutz:

This letter is written regarding a storm water inspection conducted by Sam Marotta, Brittany Turner, and Paul Hafner of the Ohio EPA at Oakwood Avenue from Marion Road to Columbus Street on May 20, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Please ensure the disturbance noted in Figure 1 is properly maintained with sediment and/or erosion controls to minimize off site sedimentation and vehicle tracking.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Oakwood Avenue 5-20-2013




Figure 1: Sediment requiring containment on south side of site.