

John Kasich, Governor  
Paul Taylor, Lt. Governor  
Chris Mitchell, Director

June 14, 2013

Barry Nutter  
The Nutter Company LLC  
441 Kiesel Court  
Powell, OH 43065

**Re: Construction Storm Water Inspection at Car Wash Depot/ Delaware County  
Permit Number: 4GCO00093\*AG**

Dear Mr. Nutter:

This letter is written regarding a storm water inspection conducted by Paul Hafner and Sam Marotta of the Ohio EPA at Car Wash Depot located at Oientangy Crossing Retail Center on June 4, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- Failed silt fence was noted along the northern and southern sides of the site. Corrective measures must be implemented within three days from receipt of this letter (See Figure 1 and 2).
- The apparent sediment pond is not fully installed. Please ensure completion within seven days from receipt of this letter. The pond must be modified for sediment control with the installation of the proposed skimmer within seven days (See Figure 3).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. This specifically applies to the stockpile on the south end of the project.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Car Wash Depot 6-4-13


Copyright 2008  
California State University  
in the State  
Department of Geology



**Figure 1 Failed Silt Fencing**



**Figure 2 Failed Silt Fencing**



**Figure 3 Sediment Pond not Complete**