



100 years and moving forward

John E. Kasich, Governor
Mike Taylor, Lt. Governor
Scott J. Wolff, Director

June 24, 2013

Tucker Bohm
The Daimler Group
1533 Lake Shore Drive
Columbus, OH 43204

**RE: Construction Storm Water Inspection at Sarcom/ Franklin County
Permit Number: 4GC04054*AG**

Dear Mr. Bohm,

This letter is written regarding a storm water inspection conducted by Paul Hafner and Jerome Hoke of the Ohio EPA at Sarcom located on the northeast corner of New Albany Road East and Souder Road on June 12, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Our staff noted failed silt fencing along the north east corner, eastern side of site, and the southern end of the site. Please ensure corrective measures are implemented to repair or replace the failed silt fence within three days of receipt of this letter. (**See Figure 1, 2, and 3**).
- The sediment pond is not completed according to the approved plan. Please ensure completion within seven days from receipt of this letter. The pond must be modified for sediment control with the installation of the proposed skimmer within designated time frame. (**See Figure 4**).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

Tucker Bohm
The Daimler Group
Page 2

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (*email preferred*) to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Sarcom 6-12-2013



Figure 1 Failed Silt Fencing Northern Portion of Site




Figure 2 Failed Silt Fencing Eastern Portion of Site



Figure 3 Failed Silt Flowing Southern Channel



Figure 4 Incomplete Sediment Pond