



John R. Kasich, Governor
Rick Taylor, Lt. Governor
Scott J. Lesly, Director

July 9, 2013

Andrew Walther
Nationwide Realty Investors
375 N. Front Street
Columbus, OH 43201

**Re: Construction Storm Water Inspection at Hilliard Woods (2) / Franklin County
Permit Number: 4GC04097*AG**

Dear Mr. Walther:

This letter is written regarding a storm water inspection I conducted at Hilliard Woods (2) located at 2070 Wilson Road on June 6, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The inspection was prompted via an anonymous complaint brought to my attention regarding a broken water line associated with recent grading activities along Worthington-Galena Road. Based on my site evaluation on June 6, 2013, I noted the water from the broken main was routed to the sediment basin and discharged into Miliken Run. I later found out the broken main was repaired within 48 hours.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Hilliard Woods (2) 6-24-13