



Mike DeWine, Governor
Richard Cordell, Lt. Governor
Harry Kallipolitis, Director

July 26, 2013

Nicholas Domenick
City of Columbus- Department of Public Utilities
910 Dublin Road
Columbus, Ohio 43215

Re: Construction Storm Water Inspection at 3rd Avenue and Edgehill Road / Franklin County. Permit Number: 4GC03803 *AG

Dear Mr. Domenick:

This letter is written regarding a storm water inspection conducted by Sam Marotta and Paul Hafner of the Ohio EPA at 3rd Avenue and Edgehill Road, located from Norton Avenue to Olentangy River Road, and Edgehill Road on July 10, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Please ensure all storm drains are properly covered with inlet protections to minimize off site sedimentation (See Figures 1 and 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm 3rd Avenue and Edgehill Road 7-10-2013




Figure 1: Non-functioning cover.



Figure 2: Insufficient sediment control.