



10 years and moving forward

John E. Kasida, Governor
Mary Taylor, Lt. Governor
Scott J. Nail, Director

July 23, 2013

Dave Warren
McDonalds USA LLC
2 Easton Oval, Suite 200
Columbus, OH 43219

**Re: Construction Storm Water Inspection at McDonald's Restaurant-Obetz / Franklin County
/ Permit Number: 4GC04043 *AG**

Dear Mr. Warren:

This letter is written regarding a storm water inspection conducted by Rachel Bellis and Elizabeth Pleta of the Ohio EPA at McDonald's Restaurant – Obetz located at 5090 Groveport Road on July 2, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Our staff observed an area of concrete disposal that lacked proper containment (See **Figure 1**). If future onsite disposal is necessary, containment measures such as a pit impoundment are expected.
- It appears that inlet protections throughout the project have become overburdened and require maintenance (see **Figure 2**).

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm McDonalds Restaurant Obetz 7-2-13




Figure 1: Areas used for concrete washout require containment.



Figure 2: Sediment is running off site into roadways, and the existing inlet protection measures are overburdened and require maintenance.