



40 years and movin' forward

John R. Kasich, Governor
Amy Lovler, Lt. Governor
Scott J. Hatly, Director

July 30, 2013

Mark Bush
Columbus (Parsons) DG LLC
361 Summit Boulevard, Suite 110
Birmingham, AL 45243

Re: Construction Storm Water Inspection at Columbus (Parsons) Dollar General/ Franklin County. Permit Number: 4GC04063*AG

Dear Mr. Havens:

This letter is written regarding a storm water inspection conducted by Elizabeth Pleta and Rachel Bellis of the Ohio EPA at Columbus (Parsons) Dollar General located at 1578 Parsons Avenue on July 10, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- It appears that the perimeter along the west side of the site is void of any sediment controls and will require installation at this time (See Figure 1). Please ensure completion within three (3) days of receiving this letter.
- It appears the silt fencing in the southwest corner has become overburdened and will require maintenance at this time (See Figure 2).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Columbus (parsons) Dollar General 7-10-13

Central District Office • 50 West Town Street • Suite 700 • P.O. Box 1049 • Columbus, OH 43216-1049
www.epa.ohio.gov • (614) 728-3778 • (614) 728-3898 (fax)



Figure 1 West side of site, adjacent to Parsons Avenue, requiring sediment controls.



Figure 2 Overburdened silt fence on the southwest corner of site requiring maintenance.