

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 8/5/13 Permit # 16C04639-A6

Site Name: POWER Plant waterfront

Site Address: 919 South Main Street Lima, OH Miami, OH

People Contacted On Site: \_\_\_\_\_

Phone: \_\_\_\_\_ E-mail: \_\_\_\_\_

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				NO one on site.
Coverage Letter				
SWP3				
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 1.6

3. Site Status: Clearing/grubbing      Rough Grading      Storm sewers in  
 Streets in      Utilities installed      Final Grade      Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective?      All      Some      None      No BMPs

Explain: \_\_\_\_\_

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? NO      8. Was an NOV issued? NO

Additional notes/comments:

Project Not started