



September 3, 2013

Steve Fuller
TH Midwest Inc
2600 Corporate Exchange Drive, Suite 170
Columbus, Ohio 43231

**RE: Construction Storm Water Inspection at Turkey Hill #717 / Franklin County
Permit Number: 4GC04026*AG**

Dear Mr. Fuller:

This letter is written regarding a storm water inspection conducted by Sam Marotta and Jerome Hoke of the Ohio EPA at Turkey Hill #717 at 950 Georgesville Road on July 31, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Our staff noted the recent installation of the skimmer in the sediment basin for purposes of sediment control. The open trench, through the embankment, must be backfilled immediately. The ONLY discharge from this impoundment must be through the skimmer during the construction phase of the project.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely

Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/Slw Turkey Hill #717 7-31-13