



John E. Rosen, Governor
Mary Taylor, Lt. Governor
Robert Naby, Director

September 9, 2013

Bill Heifner
Riener Construction
2164 City Gate Drive
Columbus, Ohio 43219

RE: Construction Storm Water Inspection at Chesrown Chevrolet, Buick & GMC/ Delaware County. Permit #: 4GCO00099*AG

Dear Mr. Heifner,

This letter is written regarding a storm water inspection conducted by Jerome Hoke and Samuel Marotta of the Ohio EPA at Chesrown Chevrolet, Buick & GMC located at the intersection of Hull Drive and Route 23 on August 14, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- As noted in a previous letter, a short segment of silt fence on the eastern portion of the site is no longer entrenched and requires maintenance (See Figure 1). Maintenance is required within three (3) days from receipt of this letter.
- The superintendent on site discussed with us the source of the pipe on the southwest corner of the site (See Figure 2) and future plans to control its output.
- Please continue to ensure positive flow of storm water to all basins intended for sediment control.


If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/islw Chesrown Chevrolet/ Buick GMC 8-14-13



Chesrown Chevrolet, Buick & GMC
Olmstead River Watershed
Photo by Jerome Hake
7/8/13

Figure 1: **Alt fence on east side requires manual wire installation.**



Figure 2: **Entire pipe on southwest corner of the site does not discharge turbid water.**