



John R. Kasich, Governor  
Macy Taylor, Lt. Governor  
Scott J. F.                      ctor

September 24, 2013

Jim Lipnos  
Homewood Corporation  
2700 E Dublin-Granville Road, Suite 300 A  
Columbus, OH 43231

**Re: Construction Storm Water Inspection at Wyandotte Woods Section 8/ Franklin County,  
Permit Number: 4GC04101 \*AG**

Dear Mr. Lipnos:

This letter is written regarding a storm water inspection conducted by Elizabeth Pleta and Rachel Bellis of the Ohio EPA at Wyandotte Woods Section 8 located at 4091 Summit View Road on September 5, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- The silt fence on the east and west sides of the site has failed and will require maintenance at this time (See Figures 1, 2, & 3).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.


If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,


Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office



**Figure 1 Southwest side of site requiring silt fence maintenance.**



**Figure 2 East side of site requiring installation of permanent silt fence.**



**Figure 3 East side of site near north sediment pond requiring silt fence maintenance.**