



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

December 8, 2011

Sue Ahrman
YUSA Corporation
151 Jamison Road SW
Washington Court House, OH 43160

**Re: YUSA Corporation, Fayette County
Industrial Storm Water Permit 4GR00115*DG**

Dear Ms. Ahrman:

This letter is written in regard to an industrial storm water inspection that I conducted at YUSA Corporation, on December 6, 2011, at your facility located at 151 Jamison Road SW, in Washington Court House, Ohio. The inspection was conducted in order to determine compliance with your industrial storm water general permit. During the inspection I was escorted by Pattie Bobb. Your facility manufactures automotive parts. The following items were noted during the inspection, also please see attached pictures:

Please send me an electronic copy of your storm water pollution prevention plan (SWP3) and your spill prevention, control and countermeasure (SPCC) plan to greg.sanders@epa.ohio.gov. Please be aware that the SWP3 and SPCC should be reviewed annually or after a change in management.

Please provide a diagram should the discharge locations of the storm water drains that exit your property, also show the flows from the storm water drain near the loading docks.

Please state where the drains discharge from under the outside drum and sludge storage area.

The loading apron near the glycol secondary containment dikes appeared to be full of storm water and may not be effective if there was a large spill during unloading.

There are several trash containers located outside on the north and east side of your facility that did not have lids. Please insure all outside trash containers have lids. Several of the trash containers were full of water and trash.

There was a uncapped drum and oil storage container located near the covered drum storage area. The uncapped drum was not located under roof. The oil storage container did not have its lid closed and was very near the edge of the roof. There needs to be better housekeeping emptying the drums into the oil storage container. Oil was discharging outside of the containment area. It is recommended to move this operation further under roof.

There was a sheen (oil or fuel) on storm water that was discharging to a storm water drain in the parking lot on the north side of the building. There should be no contaminated discharges to waters of the state.

Sue Ahrman
YUSA Corporation
Page -2-

There were numerous 300 gallon empty totes stored outside at your facility. Please insure that the totes are enclosed. Some totes were not closed.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,



A handwritten signature in black ink, appearing to read 'G. Sanders', written in a cursive style.

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

c: John Woodrow, City of Washington CH WWTP

ec: Greg Sanders, DSW/CDO

GS/nsm YUSA Corporation, December 6, 2011



AMERICAN PHOTOGRAPHY

THE
ART OF
PHOTOGRAPHY

