OhioEPA
State of Ohio Environm
Northeast D
2110 East Aurora Rd.
Twinsburg, Ohio 44087
TELE: (330) 963-1200
www.epa.

OH7830212 BELL WICK BOWL 23 10/29/07

OH7830212978107

Chris Korleski, Director

October 29, 2007

RE: TRUMBULL COUNTY
BELL WICK BOWL
TRANSIENT PWS
PWS ID# OH7830212

Bellwick Bowling Lanes
6105 W. Liberty SE
Hubbard, OH 44425

Subject: Notice of Violation - Failure to Sample Drinking Water as Required for Total Coliforms

Dear Sir/Madam:

Your public water system is in violation of Rule 3745-81-21 of the Ohio Administrative Code for failure to comply with the coliform monitoring requirements:

Monitoring Period:	**July - September, 2007**
Required Coliform Sampling:	**ONE/Calendar Quarter**
Sample Results Submitted:	**NONE**

Actions required as a result of the above violation	
Step 1	**Within 30 days** issue the attached public notice of the violation in accordance with rule 3745-81-32 of the Ohio Administrative Code by the following methods: 1. Continuous posting, mail, or other direct delivery; and 2. If necessary, the system must also use any other method reasonably calculated to reach all persons served by the public water system. *The language in italic on the attached public notice is mandatory language and must be included as written.*
Step 2	Within ten (10) days of completing **Step 1** above, fill out the attached verification form and send along with a copy of the public notification issued to the District Office of the Ohio EPA.

If samples were taken, we have not received the results. Please forward a copy of the results to my attention. Late reporting is a reporting violation but if the sample was taken and a result obtained, you will not need to issue the attached public notice.

If you have any questions, please contact me at (330) 963-1242.

Sincerely,

Charlotte E. Hammar
Environmental Specialist
Division of Drinking and Ground Waters

CEH:dms

enclosures

cc: Toni Buchanan, Ohio EPA, Central Office, DDAGW
Trumbull County Health Department
Kim Etters, Ohio EPA, NEDO, DDAGW