Ohio Environmental Protection Agency

John R. Kasich, **Governor**
Mary Taylor, **Lt. Governor**
Scott J. Nally, **Director**

DDGWOH7776112689O

November 27, 2012

THE FALCON RESTAURANT AND LOUNGE
246 CASTON ROAD
AKRON, OH 44319

Re: SUMMIT COUNTY
THE FALCON LOUNGE
Transient Noncommunity Water System
PWS ID: OH7776112
STU ID: 7758948

DELINQUENCY NOTICE - ACTION REQUIRED

Subject: Failure to Monitor Drinking Water

THE FALCON LOUNGE is in violation of Ohio Administrative Code Rule 3745-81-23 for failing to monitor your drinking water during the June 1, 2012 to October 31, 2012 monitoring period and/or report results for the following contaminants: NITRATE (AS N).

THE FALCON LOUNGE must promptly take the following actions.

A. If sample was taken during this monitoring period,
a. Call your laboratory and have them submit the results to Ohio EPA.
b. Contact this office at (614) 644-2752 to consult with us on this issue.

- OR -

B. If sample was not taken during or after this monitoring period,
a. Immediately take a sample of your drinking water from the first tap following treatment.
b. Submit the sample for analysis to a certified laboratory on the enclosed list.

- OR -

C. If sample was taken after this monitoring period, contact this office at (614) 644-2752.

Your prompt attention to this matter is appreciated. Continued failure to sample during your scheduled time period may lead to enforcement which may include penalties. If you have questions, please call me at (614) 644-2752.

Sincerely,

Wendy Sheeran

Wendy Sheeran
Division of Drinking and Ground Waters

Enclosure: Laboratory List
cc: Superintendent/Manager; DDAGW-NEDO file; DDAGW-CO file

50 West Town Street, Suite 700
P.O. Box 1049
Columbus, Ohio 43216-1049

614 | 644 2752
614 | 644 2909 (fax)
www.epa.ohio.gov

Printed on Recycled Paper

Ohio EPA is an Equal Opportunity Employer

Printed in-house