Ohio Environmental Protection Agency

John R. Kasich, **Governor**
Mary Taylor, **Lt. Governor**
Scott J. Nally, **Director**

DDGWOH5935512674 7

November 27, 2012

HERSHS COUNTRYSIDE RESTAURANT
7338 US RTE 42 N
MT GILEAD, OH 43338

Re: MORROW COUNTY
HERSHS COUNTRYSIDE RESTAURANT PW
Transient Noncommunity Water System
PWS ID: OH5935512
STU ID: 5956778

DELINQUENCY NOTICE - ACTION REQUIRED

Subject: Failure to Monitor Drinking Water

HERSHS COUNTRYSIDE RESTAURANT PWS is in violation of Ohio Administrative Code Rule 3745-81-23 for failing to monitor your drinking water during the June 1, 2012 to October 31, 2012 monitoring period and/or report results for the following contaminants: NITRITE (AS N).

HERSHS COUNTRYSIDE RESTAURANT PWS must promptly take the following actions.

A. If sample was taken during this monitoring period,
a. Call your laboratory and have them submit the results to Ohio EPA.
b. Contact this office at (614) 644-2752 to consult with us on this issue.

- OR -

B. If sample was not taken during or after this monitoring period,
a. Immediately take a sample of your drinking water from the first tap following treatment.
b. Submit the sample for analysis to a certified laboratory on the enclosed list.

- OR -

C. If sample was taken after this monitoring period, contact this office at (614) 644-2752.

Your prompt attention to this matter is appreciated. Continued failure to sample during your scheduled time period may lead to enforcement which may include penalties. If you have questions, please call me at (614) 644-2752.

Sincerely,

Wendy Sheeran

Wendy Sheeran
Division of Drinking and Ground Waters

Enclosure: Laboratory List
cc: Superintendent/Manager; DDAGW-CDO file; DDAGW-CO file

50 West Town Street, Suite 700
P.O. Box 1049
Columbus, Ohio 43216-1049

614 | 644 2752
614 | 644 2909 (fax)
www.epa.ohio.gov