Ohio Environmental Protection Agency

John R. Kasich, **Governor**
Mary Taylor, **Lt. Governor**
Scott J. Nally, **Director**

DDGWOH3233112730 2

July 24, 2013

UNIVERSAL GOLF
921 S Main St
FINDLAY, OH 45840

Re: HANCOCK COUNTY
OAK MALLETT GOLF CLUB
Transient Noncommunity Water System
PWS ID: OH3233112
STU ID: 3260801

DELINQUENCY NOTICE - ACTION REQUIRED

Subject: Failure to Monitor Drinking Water

OAK MALLETT GOLF CLUB is in violation of Ohio Administrative Code Rule 3745-81-23 for failing to monitor your drinking water during the January 1, 2013 to May 31, 2013 monitoring period and/or report results for the following contaminants: NITRATE (AS N).

OAK MALLETT GOLF CLUB must promptly take the following actions.

A. If sample was taken during this monitoring period,
a. Call your laboratory and have them submit the results to Ohio EPA.
b. Contact this office at (614) 644-2752 to consult with us on this issue.

- OR -

B. If sample was not taken during or after this monitoring period,
a. Immediately take a sample of your drinking water from the first tap following treatment.
b. Submit the sample for analysis to a certified laboratory on the enclosed list.

- OR -

C. If sample was taken after this monitoring period, contact this office at (614) 644-2752.

Your prompt attention to this matter is appreciated. Continued failure to sample during your scheduled time period may lead to enforcement which may include penalties. If you have questions, please call me at (614) 644-2752.

Sincerely,

Wendy Sheeran

Wendy Sheeran
Division of Drinking and Ground Waters

Enclosure: Laboratory List
cc: Superintendent/Manager; DDAGW-NWDO file; DDAGW-CO file

50 West Town Street, Suite 700
P.O. Box 1049
Columbus, Ohio 43216-1049

614 | 644 2752
614 | 644 2909 (fax)
www.epa.ohio.gov

Printed on Recycled Paper

Ohio EPA is an Equal Opportunity Employer

Printed in-house