



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

August 28, 2007

Re: Muskingum County
Village of New Concord
Reconnaissance Inspection
Correspondence (PWW)

Mr. John Huey, Village Administrator
Village of New Concord
2 West Main Street
P.O. Box 10
New Concord, Ohio 43762

Dear Mr. Huey:

On August 10, 2007, I conducted a reconnaissance inspection at the New Concord WWTP. I was accompanied by Mr. Tim Campbell of the Ohio EPA, Southeast District Office; and Mr. Jeff Wiler, Operator, Village of New Concord.

Many improvements from the previous inspection were noted and other improvements were going on at the time of inspection.

After speaking with Mr. Chris Huebner by telephone, it was also noted the Village of New Concord is currently exploring the issue with I/I in the collection system and a report is to follow by September 15, 2007. The collection system was the only area marked "marginal" on the inspection due to the I/I problem.

If you have any questions or comments, please feel free to call me at (740) 380-5227.

Sincerely,

Scott Foster
District Representative
Division of Surface Water

SF/dh

Enclosure

c: Chris Huebner

NPDES Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0PB00028*ED	OH0021024	August 10, 2007	R	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Village of New Concord WWTP U.S. Route 40 and Cabin Hill Road New Concord, Ohio 43762	2:00 p.m.	April 1, 2002
	Exit Time	Permit Expiration Date
	3:00 p.m.	March 31, 2007

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Mr. Chris Huebner, Operator Mr. Jeff Wiler, Operator	(740) 826-7671
Name, Address and Title of Responsible Official	Phone Number
Mr. John Huey, Village Administrator 2 West Main Street, P.O. Box 10 New Concord, Ohio 43762	(740) 826-7671


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N</u> Pretreatment
<u>S</u> Records/Reports	<u>N</u> Laboratory	<u>N</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u>N</u> Other
<u>M</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See attached letter.



 Scott Foster, Inspector, Ohio EPA, Southeast District Office

8/27/07

 Date



 Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

8/28/07

 Date