



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street,
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korteski, Director

September 25, 2007

Re: Monroe County
Village of Beallsville
CEI 2008
Correspondence (PWW)

Mr. David Boyce
Village of Beallsville WWTP
P.O. Drawer E
Beallsville, Ohio 43716

Dear Mr. Boyce:

On September 4, 2007, I conducted a Compliance Evaluation Inspection for your facility. I was accompanied by Tim Campbell, Ohio EPA, and you. The following are comments from the inspection:

1. A thermometer should be installed in your sampler fridge. The temperature should be recorded daily. The sampler fridge temperature should be maintained between 38 and 42 degrees Fahrenheit.
2. The tubing on the final sampler should be replaced. The tubing showed signs of aging and had a lot of algae growth on the inside of the tubing.
3. The weirs on all the tanks should be cleaned on a regular basis. There was a large amount of sludge and slime build up on the weirs. On high rain events, this can lead to suspended solids violations in the effluent.
4. The test equipment should be calibrated daily and before each use. The calibration records should be recorded in a log book or on a bench sheet and kept in a notebook.
5. The final sampler should be programmed to operate in correlation to the effluent flow. You have recently informed this office that the sampler is out for repair and that you are grab sampling. This should be corrected ASAP and the sampler put back into service.

We also discussed with Mayor John Gramlich and the village's consultant, Val Roxby, the I/I problems the village have and possible solutions to the problem. The Ohio EPA will contact DEFA and consult the village about possible funding for sewer work and installation of ultraviolet disinfection at the wastewater plant.

Overall, since there has been minimal or no permit violations in the past year, I rate your facility as satisfactory, but you have room for improvement.

If you have any questions or comments, please feel free to call me at (740) 380-5227.

Sincerely,



Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/dh

Enclosure

c: John Gramlich, Mayor

**NPDES
Compliance Inspection Report**

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
OPA00000*GD	OH0020885	September 4, 2007	C	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Village of Beallsville WWTP County Road 1 Kings Highway Beallsville, Ohio 43716	9:30 am	March 1, 2003
	Exit Time	Permit Expiration Date
	11:00 am	February 29, 2008

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
David Boyce, Operator	740-926-9181
Name, Address and Title of Responsible Official	Phone Number
John Gramlich, Mayor Village of Beallsville PO Drawer E Beallsville, Ohio 43716	740-926-1792

C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N</u> Pretreatment
<u>S</u> Records/Reports	<u>M</u> Laboratory	<u>S</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u>N</u> Other
<u>N</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See Attached Letter.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

9/24/07

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

9/24/07

Date