



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

September 25, 2008

Re: Pike County
Village of Piketon
Ohio EPA Permit No. 0PB00031*ED
NPDES Permit No. OH0027031
Correspondence (PWW)

Mayor Bill Spencer
Village of Piketon
109 Third Street
Piketon, Ohio 45661

Dear Mayor Spencer:

On Friday, August 22, 2008, Aaron Wolfe and I conducted a reconnaissance inspection at the Piketon Wastewater Treatment Plant (WWTP) located on Old Jasper Road. Mike Shaw represented the village and assisted us during the inspection. The purpose of the inspection was to determine if the treatment plant was meeting the terms and conditions set forth in the NPDES permit.

A copy of our inspection form is enclosed with this letter. If you have any questions or comments, please contact me at (740) 380-5226.

Sincerely,

Patrick Hudnall
District Representative
Division of Surface Water

PH/dh

Enclosure

c: Village Council
c: Ronda Clemmons, Village Administrator
c: Mike Shaw, Operator

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0PB00031	OH0027031	August 22, 2008	R	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Piketon WWTP Old Jasper Rd Piketon, Ohio 45661	1:00 PM	July 1, 2006
	Exit Time	Permit Expiration Date
	1:30 PM	June 30, 2011

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Mike Shaw, Operator	740-357-0065
Name, Address and Title of Responsible Official	Phone Number
Village of Piketon 109 Third Street Piketon, Ohio 45661	740-289-8154


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>S</u> Compliance Schedules
<u>M</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u> </u> Other
<u>N</u> Collection System		

(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

At the time of the inspection, the West Trickling Filter distribution are was not operating properly. Either the distribution arm was in need of repair or it was not receiving enough flow to properly operate. I told Mike to check into the problem and get the arm working properly.


Patrick Hudnall, Inspector, Ohio EPA, Southeast District Office

9/25/08
Date


Timothy M Campbell, Reviewer, Ohio EPA, Southeast District Office.

9/25/08
Date