



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

August 21, 2007

**RE: Aircraft Plating Corp.
OHD 004 176 681
Large Quantity Generator of
Hazardous Waste
PRTC**

Gerald Ott
Aircraft Plating Corp.
1106 Clark Ave.
Cleveland, OH 44109-1824

Dear Mr. Ott:

On June 21, June 27, July 13, and July 17, 2007, I received your e-mail responses to my June 14, 2007 Notice of Violation letter. My review of these found that Aircraft Plating has documented its correction of the following violations found during the May 24, 2007 inspection:

2. OAC rule 3745-65-52(E) - Contingency plan emergency equipment.
3. OAC rule 3745-65-31 - Maintenance and operation of facility.
4. OAC rule 3745-65-33 - Testing and maintenance of equipment.
5. OAC rule 3745-273-13 (D) - Universal waste lamp containers.
6. OAC rule 3745-273-14 (E) - Universal waste lamp labeling.
7. OAC rule 3745-273-15 (C) - Demonstrate length of time universal waste has been accumulated.
8. OAC rule 3745-273-16 - Employee training for handlers of universal waste.

Your August 7, 2007 e-mail told me that the hazardous waste annual review of training will be done on September 19, 2007. Aircraft Plating will remain in violation of the following rule until this is completed:

1. OAC rule 3745-65-16(C) – Annual review of initial training.
Please submit documentation to me once this has occurred.

Aircraft Plating has addressed the following concerns:

1. This concern dealt with ensuring that only trained employees sign shipment papers such as land disposal restriction notices. Your July 17, 2007 e-mail documents that you have addressed this concern.
2. This concern dealt with job descriptions as required by OAC rule 3745-65-16(D)(2). Your July 24, 2007 e-mail and attached job description documents that you have addressed this concern.


Gerald Ott
Aircraft Plating Corp.
August 21, 2007
Page 2

3. This concern dealt with the required shipment of plating tank cleanout waste. You sent me copies of two manifests both dated July 31, 2007. One was for the shipment of 3,233 pounds of F007 waste copper cyanide to Von Roll America in East Liverpool, Ohio. The other was for 2,537 pounds of D003 waste cyanides to Heritage Environmental Services in Indianapolis, Indiana. This documents that you have addressed this concern.

You can find copies of the regulations and other information on the Division of Hazardous Waste Management web page at <http://www.epa.state.oh.us/dhwm/>.

If you have any questions, please contact me at (330) 963-1217, or robert.almquist@epa.state.oh.us.

Sincerely,



Robert Almquist
Division of Hazardous Waste Management

RA:cl

cc: Natalie Oryshkewych, DHWM, NEDO

ec: Frank Popotnik, DHWM, NEDO
Harry Sarvis, DHWM, CO
Sherry Slone, DHWM, NEDO

NOTICE:

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your facility from its obligation to comply with all applicable regulations.