



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

May 10, 2007

RE: **AVERY DENNISON**
OHD 010 836 716
RTC

Brian Franczek
Avery Dennison
1770 Foltz Industrial Parkway
Strongsville, Ohio 44149

Dear Mr. Franczek:

I have received your May 1, 2007 letter which responded to my March 22, 2007 inspection of Avery Dennison located at 15939 Industrial Parkway in Cleveland, Ohio. Avery Dennison has addressed all the issues found during that inspection as outlined below.

1. OAC rule 3745-52-11 – Hazardous waste determination.

Avery Dennison had been cited for violating this rule by having waste in at least one of its drum containment pallets without determining whether it is a hazardous waste. Your letter indicates that no waste was in this spill pad, therefore, Avery Dennison did not violate this rule. Your letter also states that this spill pad will be pressure washed as part of the closure of the hazardous waste accumulation area.

If you have any questions, please contact me at (330) 963-1217, or robert.almquist@epa.state.oh.us.

Sincerely,

Robert Almquist
Division of Hazardous Waste Management

RA:cl

cc: Natalie Oryshkewych, DHWM, NEDO

ec: Frank Popotnik, DHWM, NEDO
Harry Sarvis, DHWM, CO
Kevin Weeks, Avery Dennison

NOTICE:

Ohio EPA'S failure to list specific deficiencies or violations in this letter does not relieve your facility from its obligation to comply with all applicable regulations.