



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

March 25, 2009

Kevin Weeks  
EHS Manager  
Avery Dennison  
7600 Auburn Rd.  
Concord Twp., OH 44077

**RE: AVERY DENNISON BLDG. 22 PILOT COATING OPERATION  
OHR 000138933, LAKE COUNTY  
RCRA SMALL QUANTITY GENERATOR (SQG) CEI RETURN TO  
COMPLIANCE (RTC)**

Dear Mr. Weeks:

On March 24, 2009, Ohio EPA received your letter with attachments documenting that Avery Dennison Bldg. 22 (Avery) located at 8080 Norton Parkway, Mentor, Ohio, has achieved compliance in regard to the following violations found during Ohio EPA's inspection of Building 22 on February 12, 2009:

- 1) Ohio Administrative Code (OAC) **3745-52-34 (D) (4)** for failure to mark on two drums of hazardous waste the dates of accumulation. On February 12, 2009, Avery corrected this violation.
- 2) **OAC 3745-66-74** for failure to inspect and record on a weekly basis the inspections of hazardous waste containers located in the <180 day hazardous waste accumulation area.

Thank you for your cooperation in this matter. If you have any questions about this letter, please call me at (330) 963-1266.

Sincerely,

Kris L. Coder  
Environmental Specialist  
Division of Hazardous Waste Management

KLC:cl

ec: Nyal McKenna, NEDO, DHWM cc: Natalie Oryshkewych, NEDO, DHWM  
Harry Sarvis, CO, DHWM