



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 24, 2008

RE: COMPONENT REPAIR TECHNOLOGIES
LARGE QUANTITY GENERATOR
OHD 147 190 417
LAKE COUNTY
RTC

Mr. Cliff Smith
Component Repair Technologies
8507 Tyler Boulevard
Mentor, OH 44060

Dear Mr. Smith:

On April 24 and June 17, 2008, the Ohio Environmental Protection Agency (Ohio EPA), Division of Hazardous Waste Management, received Component Repair Technologies' (CRT) response to the Agency's March 10, 2008 partial return to compliance letter. CRT submitted a professional engineer (P.E.) certification for the piping installed to direct hazardous waste from plating and clean lines to the two hazardous waste tanks; and a P.E. certification for the secondary containment pits that serve the plating and clean lines

Ohio EPA's review of the documentation reveals that CRT has adequately demonstrated abatement of all violations discovered during the September 18, 2007 inspection. However, please be aware that since CRT violated ORC §3734.02(E) and (F), the facility is subject to all applicable general facility standards found in OAC chapters 3745-54 and 55. Additionally, at any time Ohio EPA may assert its right to have CRT begin facility-wide cleanup pursuant to the Corrective Action process under Ohio law.

Should you have any question, please feel free to call me at (330) 963-1278.

Sincerely,

Wade Balser
District Representative
Division of Hazardous Waste Management

WB:ddw

cc: Tammy Heffelfinger, DHWM, CO
ec: Natalie Oryshkewych, DHWM, NEDO