

## SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Fill in your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

MEL TATMAN PRESIDENT  
MULTI SERVICE  
1962 RADIO ROAD  
DAYTON OH 45431


2. Article Number

(Transfer from service label)

7007 0220 0001 2491 2351

## COMPLETE THIS SECTION ON DELIVERY

A. Signature


 Agent Addressee

B. Received by (Printed Name)

MEL TATMAN

C. Date of Delivery

5.18.10

D. Is delivery address different from item 1?  YesIf YES, enter delivery address below:  No


Mail

 Express Mail Registered Return Receipt for Merchandise Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

 Yes

UNITED STATES POSTAL SERVICE



First-Class Mail  
Postage & Fees Paid  
USPS  
Permit No. G-1

• Sender: Please print your name, address, and ZIP+4 in this box •

OEPA SWDO  
CATHY ALTMAN DHWM  
401 EAST FIFTH STREET  
DAYTON OH 45402 2911

7007 0220 0001 2491 2351

Postal Service  
**CERTIFIED MAIL RECEIPT**  
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at [www.usps.com](http://www.usps.com)

**OFFICIAL USE**

Postage	\$
Certified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	
Total Postage & Fees	\$

Postmark  
Here  
CA/MAR/FOR  
BP

Sent To Mei Tatman President  
 Street, Apt. No.,  
 or PO Box No. Multi-Service 1962 Radio Rd.  
 City, State, ZIP+4 Canton, OH 45431

## Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

### **Important Reminders:**

- Certified Mail may **ONLY** be combined with First-Class Mail<sup>®</sup> or Priority Mail<sup>®</sup>.
- Certified Mail is *not* available for any class of international mail.
- **NO INSURANCE COVERAGE IS PROVIDED** with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a *Return Receipt* may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS<sup>®</sup> postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "*Restricted Delivery*".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

**IMPORTANT: Save this receipt and present it when making an inquiry.**

**Environmental  
Protection Agency**

Ted Strickland, Governor  
Lee Fisher, Lt. Governor  
Chris Korteski, Director

May 10, 2010

**Certified Mail**

Mel Tatman  
President  
Multi-Service  
1962 Radio Road  
Dayton, Ohio 45431

**RE: Continued Compliance Evaluation Inspection - OHR000014605**

Dear Mr. Tatman:

Thank you for assisting Jeff Smith and me on the May 5, 2010, inspection of Multi-Service's Dayton, Ohio facility. The purpose of the inspection was to determine the status of activities and Multi-Service.

During the April 7, 2010, inspection Ohio EPA observed one leaking 55-gallon drum dated October 30, 2009. You placed absorbent materials on the hazardous waste spill. You stated you would either over-pack the drum or place the waste into a new drum. Since you were the only one at the facility that day, you stated you would wait until another employee was on-site the next day (Thursday, April 8, 2010) before moving the drum. During the April 21, 2010, inspection Ohio EPA observed the same drum still surrounded by absorbent materials with waste visible under the pallet. During that inspection, you and Joe LaMantia stated the liquid on the floor was rainwater that had run down the drums and become rusty. Ohio EPA explained that waste had leaked down the pallet under the drum and the waste was very similar to the hazardous waste from a previous drum leak observed during the January 12, and 21, 2010, inspections. We recommended you move the drum to verify where the leak was coming from.

During the May 5, 2010, inspection Ohio EPA again observed the same drum with waste visible under the pallet still surrounded by absorbent materials. While it appears the active leak has stopped, Multi-Service has still not addressed concerns of the integrity of the drum or the waste on the floor.

Page 1 of 5  
Multi-Service  
May 10, 2010

Multi-Service continues to store fifty (50) 50 totes and twenty two (22) drums of hazardous wastes on-site. Of those, thirty-four (34) totes and nineteen (19) drums continue to exceed the 90-day storage limit.

Based on this inspection, Multi-Service continues to be in violation of the following hazardous waste regulations:

**1. Treatment, storage, and disposal facility Ohio Revised Code (ORC) 3734.02(E)(2) and (F) state in part:**

(E)(2) No person shall establish or operate a hazardous waste facility for the storage, treatment, or disposal of any hazardous waste, without a hazardous waste facility installation and operation permit issued in accordance with section 3734.05 of the Revised Code.

(F) No person shall store, treat, or dispose of hazardous waste identified or listed under this chapter and rules adopted under it, regardless of whether generated on or off the premises where the waste is stored, treated, or disposed of, except at or to any permitted hazardous waste facility.

Multi-Service continues to illegally store thirty-four (34) hazardous waste totes and nineteen (19) hazardous waste drums beyond the 90-day storage limit. Therefore, Multi-Service continues to be in violation of ORC 3734.02(E)(2) and (F).

<b>Tote Date</b>	<b>90-Day Storage Date</b>	<b>As of May 5, 2010, Number of Days Exceeding the 90-Day Storage Limit</b>
October 19, 2009	January 17, 2010	108
October 30, 2009	January 28, 2010	97
November 3, 2009	February 1, 2010	93
2 Totes – November 4, 2009	February 2, 2010	92
November 5, 2009	February 3, 2010	91
November 9, 2009	February 7, 2010	87
2 Totes – November 10, 2009	February 8, 2010	86
2 Totes – November 11, 2009	February 9, 2010	85
November 16, 2009	February 14, 2010	80
November 17, 2009	February 15, 2010	79
November 18, 2009	February 16, 2010	78

<b>Tote Date</b>	<b>90-Day Storage Date</b>	<b>As of May 5, 2010, Number of Days Exceeding the 90-Day Storage Limit</b>
November 20, 2009	February 18, 2010	76
November 24, 2010	February 22, 2010	72
November 30, 2009	February 28, 2010	66
December 1, 2009	March 1, 2010	65
December 2, 2009	March 2, 2010	64
December 7, 2009	March 7, 2010	59
December 9, 2009	March 9, 2010	57
December 14, 2009	March 14, 2010	52
December 15, 2009	March 15, 2010	51
December 21, 2009	March 21, 2010	45
December 22, 2009	March 22, 2010	44
December 23, 2009	March 23, 2010	43
December 29, 2009	March 29, 2010	37
January 4, 2010	April 4, 2010	31
January 6, 2010	April 6, 2010	29
January 7, 2010	April 7, 2010	28
January 12, 2010	April 12, 2010	23
January 13, 2010	April 13, 2010	22
January 19, 2010	April 19, 2010	16
January 26, 2010	April 26, 2010	9
<b>Drum Date:</b>		
9 Drums – October 2, 2009	December 31, 2009	125
October 30, 2009	January 28, 2010	97
2 Drums – November 11, 2009	February 9, 2010	85
2 Drums – December 2, 2009	March 2, 2010	64

Drum Date	90-Day Storage Date	As of May 5, 2010, Number of Days Exceeding the 90-Day Storage Limit
December 28, 2009	March 28, 2010	38
January 6, 2010	April 6, 2010	29
January 13, 2010	April 13, 2010	22
January 14, 2010	April 14, 2010	21
January 26, 2010	April 26, 2010	9

Because Multi-Service has violated ORC 3734.02(E) and (F), Multi-Service is subject to all applicable general facility standards found in OAC Chapters 3745-54 and 55. Additionally, at any time Ohio EPA may assert its right to have Multi-Service begin facility-wide cleanup pursuant to the Corrective Actions process under Ohio law.

- Conditions of containers, OAC 3745-66-71:** If a container holding hazardous waste is not in good condition, or if it begins to leak, the owner or operator must transfer the hazardous waste from such container to a container that is in good condition or manage the waste in another manner that complies with the requirements of Chapters 3745-65 to 3745-69 and 3745-256 of the Administrative Code.

**General inspection requirements, OAC 3745-65-15(C):** The owner or operator must remedy any deterioration or malfunction of equipment or structures which the inspection reveals. Such remedies must be on a schedule which ensures that the problem does not lead to an environmental or human health hazard. Where a hazard is imminent or has already occurred, remedial action must be taken immediately.

Multi-Service failed to adequately address the leaking drum from the April 7, 2010, inspection. **Therefore, Multi-Service is in violation of OAC 3745-66-71 and 3745-65-15(C).**

Please be aware, all wastes stored at the facility (for example, in the WWTU, equalization tanks, mix tank, DAF unit, and floor pit, all trenches in the floor, the various tanks on-site, all sump pits and any waste textiles) must all be properly characterized to determine which wastes are hazardous. Any product materials or remaining textiles on-site that are to be disposed of must also be properly characterized to determine whether the wastes are hazardous. Failure to properly characterize any waste will cause Multi-Service to be in violation of OAC 3745-52-11.

Multi-Service also continues to be in violation of ORC Chapter 6111 and OAC rule 3745-42-02 for failing to comply with Multi-Service's July 26, 2005, PTI Special Condition for compliance with the applicable tank standards of OAC rules 3745-66-90 through 3745-66-101.

Please be aware, Multi-Service must comply with the Cessation of Regulated Operations requirements set forth in Ohio Administrative Code 3745-352.

Sincerely,



Cathy L. Altman  
Division of Hazardous Waste Management

ec: DHWM Data Entry/Facility File  
Brian Ball, AGO  
Kelly Smith, DHWM, CO

**NOTICE:**

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your company from having to comply with all applicable regulations.

CLA/bp

