



State of Ohio Environmental Protection Agency

**Southeast District Office**

2195 Front Street  
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

**SCIOTO COUNTY  
SCIOTO SANITATION LANDFILL**

**INTEROFFICE COMMUNICATION**

**TO: DSIWM-SEDO FILE**  
**FROM: CLINT SHUFF, DSIWM-SEDO**  
**SUBJECT: SCIOTO SANITATION LANDFILL - #73-00-01**  
**DATE: December 29, 2008**

On December 8, 2008, I conducted an inspection of the Scioto Sanitation Landfill as required by Ohio Administrative Code (OAC) Rule 3745-27-14(A) to determine compliance with the solid waste disposal law and rules. I was accompanied by Bob Large, Harry Smail and Karen Mohr with Ohio EPA's Remediation Unit.

The Scioto Sanitation Landfill has not been closed in accordance with Chapter 3745-27 of the OAC. The enforcement case is completed and all responsible parties are deceased. Since final closure was not accomplished in accordance with the earlier Rule requirements, closure must now be performed in accordance with OAC Rule 3745-27-11, as effective June 1, 1994.

During this inspection, the haul road approximately 200 feet north of the office has washed away. To gain access to the landfill, one must enter the landfill approximately 150 feet south of the office building or cross a ledge up the haul road. I observed that solid waste is exposed on the landfill as well as in the tributary that leads into the stream on Lick Run Lyra Road. Leachate was observed in several areas draining into the eroded rills that lead into the tributary. Several seeps were observed in the toe of the landfill. I estimated that 10 (GPM) of leachate is entering the unnamed tributary to Lick Run Lyra Creek. The weather was approximately 40 degrees and partly cloudy.

Some of the rills on the haul road are three feet deep. Caution should be used when walking on the haul road. The rills next to the landfill or toe and between the haul road are as deep as 10 feet. I am also concerned about the existing slopes of the landfill; they are currently very steep, and may eventually fail and slip. I observed wastes from the landfill in the tributary. Wastes can be seen while walking on the landfill.

Violations of OAC Rules 3745-27-10, 3745-27-11(F)(G)(H)(I)(J), 3745-27-12, 3745-27-15, 3745-27-16 and OAC 3745-27-19 have occurred.

CS/jg