



Environmental  
Protection Agency

Ted Strickland, Governor  
Lee Fisher, Lt. Governor  
Chris Korleski, Director



\*1PZ0008020070705\*

PREBLE NEW PARIS CONVENIENT FOODS WARE, MAUREEN 2007/07/05

File: Preble Co  
New Paris Food Mart  
Sewerage



State of Ohio Environmental Protection Agency

**Southwest District Office**

401 E. Fifth St.  
Dayton, Ohio 45402

TELE: (937) 285-6357 FAX: (937) 285-6249  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

July 5, 2007

Winta Singh  
New Paris Food Mart  
9592 US 40 West  
New Paris, Ohio 45347

RE: New Paris Food Mart Reconnaissance Inspection

Dear Mr. Singh:

On July 5, 2007, I conducted a Compliance Evaluation Inspection at the New Paris Food Mart WWTP facility. A copy of my inspection report is enclosed. The inspection report contains two marginal, but no unsatisfactory ratings.

Within 30 days of the date of this letter, please indicate in writing what you plan to do to address the issues that caused the marginal ratings.

If you have any questions or comments concerning the contents of this letter, please feel free to contact me this office.

Sincerely,

~~Maureen M. Ware~~  
Division of Surface Water

enclosures

cc: Preble County Health Dist.





State of Ohio Environmental Protection Agency  
Southwest District Office

NPDES Compliance Inspection Report


Section A: National Data System Coding					
Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
1PZ00080	OH0118985	07/05/2007	R	S	2

Section B: Facility Data		
Name and Location of Facility Inspected	Entry Time	Permit Effective Date
New Paris Food Mart 9592 US 40 West New Paris, Ohio 45347	9:45 am	8/1/2002
	Exit Time	Permit Expiration Date
	10:05 am	07/31/2007
Name(s) and Title(s) of On-Site Representatives	Phone Number(s)	
Ernest W. Booth	260-519-1427	
Name, Address and Title of Responsible Official	Phone Number	
Winta Singh 9592 US 40 West New Paris, Ohio 45347	937-437-5700	

Section C: Areas Evaluated During Inspection					
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)					
S	Permit	N	Flow Measurement	N	Pretreatment
N	Records/Reports	N	Laboratory	N	Compliance Schedule
M	Operations & Maintenance	S	Effluent/Receiving Waters	S	Self-Monitoring Program
M	Facility Site Review	S	Sludge Storage/Disposal	N	Other
N	Collection System				

**Section D: Summary of Findings (Attach additional sheets if necessary)**

The WWTP is rusting badly. The wall between the aeration basin and the clarifier has large holes rusted through the wall above the water line. When the wall between the aeration basin and the clarifier rusts below the water line, the WWTP will no longer be able to properly function. The sand filters appeared to be very slowly draining as there was standing water with duckweed on the surface. The sand filters should have material on the surface of the sand removed so that the water may filter properly.

Inspector	Reviewer
	
Maureen M. Ware Division of Surface Water Southwest District Office	Martyn Burt Compliance & Enforcement Supervisor Division of Surface Water Southwest District Office
Date	Date
7/5/17	



11