



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 17, 2008

RE: REPUBLIC ENGINEERED PRODUCTS
DAPC FACILITY ID # 02 47 08 0229
RETURNED TO COMPLIANCE:
EMISSIONS UNIT P081 –
BLOOM REHEAT FURNACE

Mr. Jay Lawniczak
Environmental Manager
Republic Engineered Products
1807 E. 28th Street
Lorain, OH 44055

Dear Mr. Lawniczak:

This letter is to acknowledge that Republic Engineered Products ("Republic") has brought the Bloom reheat furnace back into compliance with the NOx limit of 0.132 lb/MMBtu.

The Ohio EPA, Northeast District office, issued two notices of violation dated January 2, 2008 and March 12, 2008, for not complying with the aforementioned limit.

Republic had submitted a compliance plan dated January 21, 2008.

The Ohio EPA, Northeast District office, received and completed of review the NOx emissions testing report. The testing was conducted on April 8, 2008. The average emissions rate of NOx, based on three, one-hour test runs was 0.044 lb/MMBtu.

If you have any questions concerning this letter, please contact me at (330) 963-1187.

Sincerely,

Tony Becker
Environmental Specialist
Division of Air Pollution Control

TB:bo

cc: Lisa Holscher, U.S. EPA Region V

ec: Bob Princic, DAPC-NEDO
Dennis Bush, DAPC-NEDO
Tom Kalman, DAPC-CO