



4GR0036720100210

2010/02/10

4GR00367

TIGERPOLY MFG INC



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

February 10, 2010

Brian Klei
Tigerpoly Manufacturing, Inc.
6231 Enterprise Parkway
Grove City, OH 43123-9271

**Re: Tigerpoly Manufacturing, Inc. / Franklin County
Industrial Storm Water Permit 4GR00367*DG**

Dear Mr. Klei:

This letter is written in regard to the storm water inspection that I conducted at Tigerpoly Manufacturing, Inc., located at 6231 Enterprise Parkway, in Grove City, Ohio. The inspection was conducted on February 3, 2010, to determine compliance with your industrial storm water permit. You stated that you company manufactures automotive parts and flexible tubing. I did not note any discharges from your facility to a storm water drain or waters of the state.

The following items were noted during the inspection:

1. Your company had several drums stored outside without secondary containment and one drum did not have a cap on the drum. Please provide secondary containment for the drums or store them inside. The drums should have lids or covers. Please see attached pictures.
2. The "trash trap" collected storm water run-off from the trash collection bin area and pumped the screened storm water to a drainage ditch along the rear of our company. Please be aware that no pollutants shall be discharged to waters of the state. It is recommended that the suction end of the hose be placed at such a level that it will not pump the scum off the top of the collected storm water nor the grit from the very bottom of the tank. Also, the material collected from the screen shall be disposed of in a landfill. Please see attached pictures.
3. It was noted that your company has four tanks for the storage of plastic pellets.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director



Brian Klei
Tigerpoly Manufacturing, Inc.
Page 2-

4. It was noted that there is a storm water sediment basin located at the southern boundary of your property.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,



Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosures

c: Jeff Bohne, DSW/CDO


GS/nsm Tigerpoly Mfg., Inc., February 3, 2010

Tigerpoly Mfg., Inc.
Store drums w/lids & secondary containment
Scioto River Watershed
February 5, 2010
Photo by: Greg Sanders



Tigerpoly Mfg., Inc.
Store drums w/lids & secondary containment
Scioto River Watershed
February 5, 2010
Photo by: Greg Sanders





Tigerpoly Mfg., Inc.
Trash trap discharge
Scioto River Watershed
February 5, 2010
Photo by: Greg Sanders



Tigerpoly Mfg., Inc.
Trash trap discharge
Scioto River Watershed
February 5, 2010
Photo by: Greg Sanders

