



\*4GCO000120100920\*

2010/09/20

4GCO0001

THE INN AT OLENTANGY TRAIL



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898  
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049  
Columbus, OH 43216-1049

September 20, 2010

Roger McClain  
Jerry McClain Companies  
51 North Third Street Ste 701  
Newark, OH 43055

**Re: Construction Storm Water Inspection at the Inn at Olentangy Trail  
Delaware County  
Permit Number: 4GCO00018\*AG**

Dear Mr. McClain:

This letter is written regarding a storm water inspection conducted by Abigail Tamkin and Megan Reising of the Ohio EPA at the Inn at Olentangy Trail located at the intersection of US 23 and Corduroy Drive in Delaware County, Ohio on August 31, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- The protection for the catch basin in the southwestern corner of the site requires maintenance to ensure proper sediment control (see figure 1).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm The Inn at Olentangy Trail 8-31-2010

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director






Figure 1. The sediment protection for the catch basin requires maintenance

