



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

August 24, 2010

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898  
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049  
Columbus, OH 43216-1049

Randolph B. Spencer  
Dunlop and Johnston  
5498 Innovation Drive  
Valley City, OH 44280

**Re: Construction Storm Water Inspection at Ohio Army National Guard Regional Training Institute/ Franklin County  
Permit Number 4GC03176\*AG**

Dear Mr. Spencer:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley and Mike Shields of Ohio EPA at Ohio Army National Guard Regional Training Institute located at DSCC – 3900 East Broad Street, Columbus, Ohio on August 11, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following was noted:

**Sediment and Erosion Control:**

- The detention basin noted onsite must be modified to address sediment control via the installation of a temporary riser. This will allow for additional settling time for the suspended solids to settle prior to a final discharge from the site (Figure 1 and 2).
- The silt fence running adjacent to Eighth Boulevard requires maintenance as it appears it is allowing sediment to flow onto the adjacent road (Figure 3).

**Post Construction Requirements:**

- The General Storm Water Permit requires specific post construction water quality treatment for all sites. Guidance regarding the post construction requirements is found at: <http://www.epa.state.oh.us/dsw/storm/CGPPCQA.aspx>. Please submit to my attention (email preferred at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us)) which practice will be installed at this site to ensure compliance with the General Permit. Please include all design criteria and calculations in your submission.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Ohio Army National Guard Regional Training Institute 8-24-10  
Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director






Ohio Army National Guard Regional  
Training Institute  
Big Walnut Creek watershed

Photo taken by Mike Shields  
8/11/2010




Figure 1: Lack of controls around outlet



Ohio Army National Guard Regional  
Training Institute  
Big Walnut Creek watershed

Photo taken by Mike Shields  
8/11/2010

Figure 2: Lack of controls around outlet allowing sediment laden water to pass through



Ohio Army National Guard Regional  
Training Institute  
Big Walnut Creek watershed

Photo taken by Mike Shields  
8/11/2010



Figure 3: Silt fence in disrepair allowing sediment to flow onto road

4...

